# Airborne Ultrasonic Sensor

The ultrasonic sensor radiates ultrasonic waves in the air, receives a reflected wave from the object, and measures the distance to the presence detection. Ultrasonic is reverberated also in the transparent objects that cannot be detected by light.

### Features of the ultrasonic sensors

- High sound pressures & sensitivity
- Small & lightweight
- High accuracy & reliability
- Low power consumption
- Temperature, humidity, dirt, etc. environment resistance

### Functions of the ultrasonic sensors

- Space transfer of the signals High-frequency type
- Measurements of transfer times
  Detections of the continuous
- signals
- Apply of the Dopplereffects
- Pulse reflection time measurement
- Measurements of Karman vortexflows

### Mounting methods of the sensor

- One sensor reflection method (T/R, dual-purpose)
- Two sensor reflection method (T/R, single-purpose)
- Two sensor opposed method (T/R, single-purpose)
- [Notes, T; transmitted, R; received]



High-Frequency Type




Low-Frequency Type

# Transmission/Reception Signal Model

### **Typical Applications**

- Object counting on the belt conveyors
- Proximity switch in the FA facilities
- Flow sensor of liquid or gas
- Fluid level sensors &
   Water level sensors
- Intrusion alarm sensors
- Automatic opening and closing door sensors
- Equipment remote control sensors
- Paper double-feed detection sensors



T:Transmitting R:Receiving T/R:Transmitting & Receiving

Items		FUS-40BT-B	FUS-40BR-B	FUS-40E	FUS-110A	FUS-200A	FUS-300A	FUS-400A	FUS-300A-PB
Designs		Drip-proof type		Open type	Matching layer type				Matching layer type
Transducers		For transmitting For receiving		T/R dual-purpose	T/R dual-purpose				T/R dual-purpose
Nominal frequency	kHz	40		40	110	200	300	400	300
Transmitting SPL	≥dB	105							
(0dB=2×10 <sup>-5</sup> Pa)		105		_	<del>-</del>				_
Receiver sensitivity	≥dB		<del>-</del> 57						
(0dB=1V/Pa)		1 -	-57	_	_				_
T/R sensitivity	≥dB	_		<b>-</b> 43	<b>-</b> 54	<b>-</b> 56	<del>-</del> 66	<del>-7</del> 4	130mVp-p
				at.30cm	at.40cm	at.20cm	at.15cm	at.10cm	at.15cm
SPL & sensitivity band	≥kHz	2	2						_
		(100dB)	(-60dB)	_	_				
Capacitance	pF	2600		2000	600	380	260	200	1700
Directional	deg.	80		40	7	7	6	6	9 ~ 13
Maximum input voltage	V	15	_	100	80	60	40	40	50
		(r.m.s)		(Pulse Vp.p.)	(Pulse Vp.p.)			(Pulse Vp.p.)	
Detection distance	m	0.2~3		0.2~4	0.4~2.5	0.2~1.2	0.1~0.6	0.08~0.3	_
Resolutions	mm	9		9	3	2	1.2	1	1.2
Operating temp. limits	°C	<b>-</b> 20~70		<del>-</del> 25~70	<b>-</b> 20~60				<b>−</b> 20~70
Storage temp. range	C	<b>−</b> 35~80		<b>-</b> 40~85	<b>-</b> 35~70				<b>−</b> 30~70
High-temp. preservation		80℃ 500h		_	70℃ 500h				85℃ 240h
Low-temp. preservation		—35℃ 500h		_	-35℃ 500h				-40°C 240h
Humidity resistance	Sensitivity variation	60℃ 90~95%RH 500h							60℃ 90~95%RH 240h
Durability	within	60℃ 85% 10Vr.m.s 500h —			-				70℃ 12Vp-p 500h
Impact resistance	3dB	Dropped from a height of 1m on the hard-wooden board 3 times							100G, three directions, three times each
Vibration resistance		Freq: $10Hz \rightarrow 55Hz \rightarrow 10Hz$ , Cycle: 1 min, Total amplitude: 1.5 mm, Conditions: XYZ each 1 h							55-500 Hz, 6 minutes, 10G, 5 hours each
Outer diameter	mm	φ17.8		φ16	φ37	φ19	φ13	φ10	φ9.9
Height	mm	1	1	12	17.2	10.8	8.8	7.4	7.3

## Notes on use

## Please contact us for other custom-made products as well.

- Sensors have directivity, so please pay attention to mounting orientation.
- The negative terminal is connected to the case and shielded, so please handle connections with care (except for FUS-40E, FUS-300A-PB).
- Shock may generate noise; use cushioning materials such as foam rubber for mounting.
- Prolonged application of DC voltage may degrade insulation resistance; avoid continuous DC voltage.
- This sensor is not suitable for underwater use.
- Specifications are subject to change without notice for product improvement.